

Tax

NORTHFIELD 32907 Northfield Blvd. Northfield, MN 55057 1-888-645-6643 1-507-645-6643

PLAINVIEW, MN **5**07-534-3195 KASSON, MN 507-634-4388

HASTINGS, MN 651-437-4164 507-582-3360 ADAMS, MN



Amount

Price

www.mnaggroup.com

SOLD TO SMIT27 JASON SMITH 23310 NORTHFIELD BLV

HAMPTON, MN 55031

Qty Description

SHIP TO

| CASE IH 2294 | SN: 9940177 | HR 5133.0 W:00 |
|-----------------------|--------------------------|----------------------|
| Sold By: ILR PO #: 22 | 94 WEAK PTO Date 7/26/23 | 3 WORK ORDER WN23927 |
| Ship By: "Tax" | #: | PRT: 6 |

Weak PTO. Debris in Hydraulic screen. Check brakes. Rattle on LH side

Replaced back of light bulbs on the dash. Replaced one fuel filter, found a leak at the crimped side of the filter. Checked and bled right brake, still had no strength in the pedal. Determined the issue was internal in the brake.

Checked charge/filter pressure: very low. Changed hydraulic filter, hydraulic pressure: okay. Checked PTO, found a bad cable and a clutch issue. Checked remote hydraulics, low pressure. Removed and inspected remote valves, resealed primary and secondary check valves.

Checked high pressure stand by: 2200. Adjusted remote kick outs. 1900-2000. Replaced 1 remote valve pivot pin. Resealed two remote valve detents. Replaced trans breather.

Removed and inspected PTO, replaced plates and resealed. Replaced PTO drum bearing and had end machined. Removed and inspected right wheel and final drive. Replaced brake pads and resealed. Reset self adjuster. Changed hydraulic oil and filters. Bled right brake. Checked PTO on dyno; low HP. No fuel flow from tank. Drained and cleaned tank and inlet screen. Redynoed 127 HP @ 998 pto. Checked Hi idle, (2290-2300).

| CU | JST LAB NT4/1 | ++ momai cuice Lab New /1 | 5968.33 |
|----|-----------------|---------------------------|---------|
| мт | SC SHOP PARTS | ** TOTAL CUST LAB NT4/1 | 3300.33 |
| F | 1 A162961 | 23.00 | 23.00 |
| F | 3 A-1981266C1 | 76.83 | 230.49 |
| F | 3 A-A67336 | 58.79 | 176.37 |
| | | ** TOTAL MISC SHOP PARTS | 429.86 |
| SE | IOP PARTS | | |
| F | 1 CAS 47395692 | FILTER, FUE YC600 22.50 | 22.50 |
| F | 1 CAS 47380629 | FILTER, HYDR YC800 178.00 | 178.00 |
| F | 2 CAS 1342783C1 | GASKET, HYDR GA-01 25.50 | 51.00 |
| F | 1 CAS A58608 | GASKET, OIL GX128 6.35 | 6.35 |

O-RING

OR-4D

6.35 2.40

4.80

CAS 579359



507-582-3360



www.mnaggroup.com

SOLD TO SMIT27

JASON SMITH 23310 NORTHFIELD BLV HAMPTON, MN 55031 SHIP TO

ADAMS, MN

| Tax D Qty | Description | | * | Price | Amount |
|--|--|--|---|---|--|
| FFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFFF | CAS 86500548 CAS 86512844 CAS 274727 CAS 86511345 CAS 89672929 CAS A48888 CAS 710230 CAS 9617873 CAS 167266 MIS 74A CAS A142869 CAS 20943310 CAS A58092 CAS 87421149 CAS 272712 CAS A64451 CAS A59005 CAS A55963 CAS A155964 CAS A155964 CAS A155964 CAS A63258 CAS A67156 CAS A167644 CAS A177635 CAS A167644 CAS A167644 CAS A167895 HAR ZK5 CAS 117-618 | O-RING O-RING O-RING O-RING C-RING D-RING D-RING, DASH PIN, HEADED- O-RING, BOSS O'RING, ORB BRAKE CLEAN RACE-BRG. BEARING, BA RING, SQUARE O-RING O-RING O-RING BUSHING, PTO RING, PTO SE O'RING, PTO RING, PTO SE O'RING, PTO SEAL, PTO RI PLATE, STEEL PLATE, FRICT BRAKE CABLE, HYDRA SWITCH; HI P SWITCH, FILT HARDWARE, GD BOLT, REAR W NUT, REA | LC-92 OR-1C OR-9C OR10A Z05-32 GR-13 GR-01 OR-9B OR-5D GX102 GK-05 GK-04 MH100 GM-13 GP-01 D-BOLT PH230 PH230 OR-1B OR-1B OR-1B OR-1B OR-1C OR10C OR10B GX102 OR10B GX128 YC800 | 1.50 .90 1.95 .81 2.10 3.555 4.60 1.855 1.15 5.39 47.000 66.95 10.00 9.80 55.25 42.00 42.07 8.30 24.75 14.50 42.25 286.00 107.00 130.00 104.00 4.35 2.90 1.40 4.35 2.90 1.40 1.40 1.40 1.40 1.40 1.40 1.40 1.4 | 3.00 3.60 3.90 1.62 14.20 14.20 14.20 10.78 47.00 663.90 10.00 130.00 253.50 284.75 286.00 104.00 130.00 130.00 130.00 130.00 14.20 253.50 253.50 253.50 253.50 253.50 253.50 104.00 104.00 104.00 104.00 105.00 104.00 105.00 104.00 105.00 105.00 106.0 |

ge 2 Continued on next page





507-582-3360



www.mnaggroup.com

SOLD TO SMIT27

JASON SMITH 23310 NORTHFIELD BLV HAMPTON, MN 55031 SHIP TO

ADAMS, MN

| Tax D Qty Description | Price | Amount |
|--|--|--|
| F 1 CAS 84599923 F 100 OIL B-73344270 F 1 CAS 47746481 ENVIRO FEE | PLUG, WINDOW GX616 5.45 HYTRAN BULK SHOP 4.24 BREATHER 39.75 ** TOTAL SHOP PARTS | 5.45 424.00 39.75 2444.10 |
| F F FREIGHT PARTS | ** TOTAL ENVIRO FEE | 25.00 15.00 40.00 |
| F Z 0627110N F Z NP5281 F Z NP5283 F Z 0707110N LABR DISC NT4/1 | ** TOTAL FREIGHT PARTS | 25.08 17.00 13.18 33.4 88.73 |
| L Z OUTSIDE REPAIR | | 439.1 |
| F 1 REPAIR SHAFT, MACHINE SHOP SUPPLIES F SHOP SUPPLIES | BU 315.00 | 315.00 |
| F SHOP SUPPLIES Payment Due Upon Receipt. Than | ak woul | 152.3 |
| rayment bue opon keceipe. Than | ik you: | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | ** SUBTOTAL | 8999.2 |
| | | |



507-582-3360

CASE

www.mnaggroup.com

SOLD TO SMIT27

JASON SMITH 23310 NORTHFIELD BLV HAMPTON, MN 55031 SHIP TO

ADAMS, MN

| | | | .0 W:00 DRDER PRT: (| 5 |
|---|---|---|---------------------------------------|-------------|
| Tax D Qty Description | | * | Price | Amoun |
| Group: 01 | | | | |
| CHECK LIGHTS | | | | |
| Installed new wiper blade. | | | | |
| Tested flasher, functioning a lights. Removed lenses and for have no buld and broken socked burnt our bulb. Right tail libulbs as needed. Left the leftime. | is it should. Inspound upper left to the transfer right to ght had burnt out to signal not func | ected wiri irn signal irn signal bulb. Rep tioning at | ing at to had blaced this | |
| CUST LAB NT4/1 | tt momat | OHOM TAD | NT0714 / 1 | 000 1 |
| SHOP PARTS | | CUST LAB | | 230.1 |
| F 1 CAS A165059 F 1 CAS D71346 | BLADE, WIPER P BULB #168 G | W111 | 64.00 2.15 | 64.0 2.1 |
| SHOP SUPPLIES F SHOP SUPPLIES | ** TOTAL | SHOP PART | .'S | 66.1 |
| Payment Due Upon Receipt. Tha | | | | 6.9 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | ** SU | BTOTAL | 303.2 |
| X | Charge Sale | ** SU | BTOTAL | 303.2 |



507-582-3360



www.mnaggroup.com

SOLD TO SMIT27

JASON SMITH 23310 NORTHFIELD BLV HAMPTON MN 55031 SHIP TO

ADAMS, MN

| Tax D Qty Description | | * Price | Amount |
|--|---|--------------|--------|
| Group: 01 | | | |
| Service call | | | |
| wont start Service Call | | | |
| | ey switch on key | switch | |
| Checked electronics, no power to k fuse. Circuit breakers: okay. Trie connector but nut was stripped out Adjusted clutch pedal stop and swi | d'to remove fire in inner connec tch. | wall tor. | |
| CUST LAB NT4/1 | ** TOTAL CUS | T LAB NT4/1 | 366.86 |
| TRKG MILES NT41 L 1 SERVICE CALL | | 125.00 | 125.00 |
| SHOP SUPPLIES F SHOP SUPPLIES | | | 12.06 |
| Payment Due Upon Receipt. Thank yo | ou! | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | ** SUBTOTAL | 503.9 |
| | | | |